

S43 - Harvey Fld

47.904868, -122.1027436

⚠ This is a snapshot of S43 as of **2025-01-27**. The information here may be outdated.

[View live page](#)

[Update content pack](#)

✈ Airport Statistics

📍 Location: Snohomish, WA

📏 Elevation: 22ft

📖 Sectional: Seattle

📅 Activation date: Dec 1945

⛽ Fuel: 100LL, A ([prices](#))

🛬 Runway 15L/33R: 2,672ft

🛬 Runway 15R/33L: 2,430ft

🛬 Runway H1: 15ft

🔓 Access: Open to the public



Tags



Featured



Food



Public



Webcam



Car Rental



Lodging

Description

Harvey Field is home to Skydive Snohomish and is also a popular GA airport serving the Seattle area. A Buzz Inn steakhouse is present on the field and downtown Snohomish with many more food and shopping options is a short walk across the river.

The grass runway (15R/33L) is only open seasonally during the summer. Confirm it is open before landing on it. Yellow Xs are on it when closed.

[Snohomish Inn](#) provides shuttle service to/from the airport. The airport website has a full list of services available here: <http://harveyfield.com/Services.aspx>.

Last updated: 2024-01-04 23:08:28 PST

Transient Parking

Transient parking is along the north-south taxiway.

Last updated: 2024-01-08 21:13:13 PST

Fuel Location

Self-serve pumps are next to the maintenance hangars on the southwest corner of the main ramp. Truck service is also available from the FBO.

Last updated: 2024-01-08 21:13:13 PST

Landing & Tie-down Fees

None

Last updated: 2024-01-04 23:07:00 PST

Crew Car Availability

Enterprise will deliver rental cars to the field.

Last updated: 2024-01-04 10:55:18 PST


WiFi Access

None

Last updated: 2024-01-04 23:07:46 PST

Airport Webcam

<http://www.harveyfield.com/WebcamImageHandler.ashx>



Comments

Touch and Goes are not permitted by the rental aircraft and also not recommended due to short field length and wires on the north end, road on the south.

Created about 1 year ago (2024-01-05 07:12:57 UTC)

Helpful count: 1 👍

Traffic can include no-radio aircraft and skydiving jump plane that will descend into the traffic area, monitor 123.00.

Created about 1 year ago (2024-01-05 07:10:45 UTC)

Helpful count: 1 👍

Midfield traffic pattern entry from the east is not recommended due to skydiving operations and heavy flight school traffic. Use standard 45 entry.

Created about 1 year ago (2024-01-05 07:09:17 UTC)

Helpful count: 1 